NASATM-58222



NASA Technical Memorandum 58222

NASA-TM-58222 19800006753

Preliminary Results of Penetrator Field Test Program—Tonopah, Nevada, April 16-28, 1979

FOR REFERENCE

Maxwell B. Blanchard, Uel Clanton, Mischelle Dalbey, Victor Rhoder, and James P. Murphy

MOOT BUT THE MALEY FROM THE ROOM

October 1979

LIBRARY COPY

MAN 2 1 1980

MANUEY RESEARCH CENTER LIBRARY, NASA MANUTON; VIRGINIA

NASA

National Aeronautics and Space Administration

Lyndon B. Johnson Space Center Houston, Texas 77058

carc: 175/14chnical Library

National Aeronautics and Space Administration

Ames Research Center Moffett Field, California 94035



Reply to Attn of:

SPT: 244-7/213

TO:

DISTRIBUTION

FROM:

SPT/James P. Murphy, Assistant Chief

Project Technology Branch

SUBJECT: Penetrator Survivability Tests

A number of activities were undertaken by Ames in FY78 with a goal of further developing the Penetrator and answering questions in key scientific and technical areas. These activities included a series of Survivability Tests conducted by Ames, the Johnson Space Center (JSC), and Sandia. The Survivability Tests have been successfully completed, and the results are quite interesting. I have enclosed a copy of the report (NASA TM 58222) describing these test results for your information. A more comprehensive description of all the Penetrator activities and results through 1979 will be prepared in the near future for distribution in the form of a NASA TM. Max Blanchard at JSC (713-483-3274) or I (415-965-6520) will be happy to answer any questions you may have.

James P. Murphy

Enclosure: NASA TM 58222

	يەشدى ئ		s:	
· •				

NASA Technical Memorandum 58222

Preliminary Results of Penetrator Field Test Program—Tonopah, Nevada, April 16-28, 1979

Maxwell B. Blanchard, Uel Clanton, and Victor Rhoder Lyndon B. Johnson Space Center Houston, Texas


Mischelle Dalbey Lunar and Planetary Institute Houston, Texas

James P. Murphy
Ames Research Center
Moffett Field, California



Scientific and Technical Information Office

1979



CONTENTS

Section																														Page
SUMMARY	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	1
INTRODUCTION	N	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•	•	•	•	•	•		•	•	•	•	•	1
PROCEDURE .	•	•	•	•	•			•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•		2
RESULTS AND	D:	IS	CU	SS	101	1	•	•	•		•	•	•	•	•	•	•	•			•	•	•	•	•	•	•	•	•	4
CONCLUSIONS	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	6
REFERENCES																														8

TABLES

Table		Page
I	PRETEST CONDITIONS	9
II	POST-TEST CONDITIONS	10
III	LOCATION OF SCRAPE MARKS ON PENETRATOR AFTER CLEARING CATCHER BLOCK BUT BEFORE IMPACTING TARGET	11
IV	STATUS OF HIGH-SPEED MOTION PICTURE FILM	12

FIGURES

Figure		Page
1	Mars penetrator (0.63 scale) configuration fired in tests at Tonopah, Nevada, in April 1979	13
2	Layout of test site. The penetrator impact points are located at one-half the radius of the rock. Test numbers are shown beneath each target arrangement	14
3	Sabot used to adapt penetrator to 7.6-centimeter (3 inch) air gun	15
4	Penetrator and sabot assembled and mounted in breech of air gun	16
5	Air gun shown in vertical position (orientation from which measurements were made) and grid frame located beneath trailer before test 6. Camera pallets are located on the ground near the front and rear of the trailer	17
6	Penetrator being fired by air gun (test 6). The blast of air which emplaces the penetrator produces the cloud of dust obscuring the grid and the target	17
7	Grid network that provided a three-dimensional frame of reference for the high-speed motion pictures. The grid consisted of 1.3-centimeter (0.5 inch) aluminum bars welded together at 15.2-centimeter (6 inch) intervals. The grid was staked to the ground to prevent movement during the tests, but airblast-produced vibration occasionally blurred the image of the grid in the films	18
8	Layout of motion picture cameras, grid frame, and penetrator impact point	19
9	Cratered area after penetrator passed through the 13-centimeter (5 inch) diameter rock shown in figure 7. The penetrator stopped approximately 4 meters (12 feet) beneath the surface after impact. Several broken fragments of the original rock are near the grid	20
10	A 1.2-meter (4 foot) diameter hole was drilled with a bucket auger adjacent to the hole made by the penetrator	21
11	One side of the hole was removed to expose a complete cross section of the hole made by the penetrator	22

Figure		Page
12	Cross section of the hole made by the penetrator in test 2. The distance from the surface of the ground to the nose of the penetrator is 323 centimeters (127 inches). The penetrator had a final orientation of 89°20' from the horizontal along a bearing of 60°. A change in direction occurred just after the penetrator passed through the 5-centimeter (2 inch) diameter rocks	23
13	Cross sections of the hole after each penetrator test	
	(a) Tests 1 to 3	24 25 26 27 28
14	A cyclographic projection showing penetrator orientations for each test. Three points were plotted for tests 5, 6, 7, 10, 11, 12, and 13: orientation in the air gun (data from table I), orientation during free flight (data from high-speed motion pictures), and final orientation (data from table II). Two points were plotted for all other tests: orientation in the air gun and final orientation. The bearing for each point is read on the outside perimeter as a compass direction. The dip angle is read along a radius from the origin to either E or W using the graduated 10° increments from 0° to 90°. The procedure used to locate these points is described in reference 6	20
	to locate these points is described in reference 6	29

SUMMARY

A series of 13 tests of 0.63-scale solid steel penetrators fired by an air gun was performed to determine the deflection caused by impact with various sizes of volcanic rocks resting on or buried within compacted sediments. All penetrators used were identical in size, shape, weight, impact velocity, and general orientation. The targets were prepared using a basalt from the Malpais lava flow in New Mexico. This basalt, a tholeite having a porosity of 20 to 30 percent, was selected because of its similarity to Martian volcanic rock.

Photographic coverage of the tests consisted of two types of high-speed motion and 70-millimeter still photography. Two cameras, each having a film speed of approximately 10 000 frames/sec, were used to obtain closeup views of the penetrator. Timing marks were exposed on the film to assist photointerpretation. The final orientation of all penetrators was measured in situ by means of a large access hole drilled adjacent to the point of impact.

The results of the tests suggest that no catastrophic penetrator failure is likely to occur and that major deflections are caused only by rocks ≥ 10 times the diameter of the impacting body.

INTRODUCTION

The purpose of these field tests was to determine the deflection caused to subscale (0.63 scale) penetrators impacting volcanic rocks of various sizes resting on top of, and within, compacted sediments. During the tests, all penetrators were identical in size, shape, weight, impact velocity, and gen-For these tests, the final orientation of the buried peneral orientation. etrators is assumed to be primarily a consequence of the size, the shape, and the depth of the rocks encountered during impact, although some variation in impact angle was documented. Previously, a theoretical study examined the capability of a penetrator to survive impact on Mars (ref. 1). On the assumption that the hazardous size range of rocks was 0.2 to 5 times the diameter of the penetrator, it was found that the probability of catastrophic penetrator failure was 10 percent. The field tests do not confirm that the size range used in the theoretical study will cause a catastrophic penetrator failure. These tests indicate that no failure is likely to occur. Major penetrator deflections are only caused by rocks 10 times and greater in diameter than the impacting body, and then deflection is highly dependent upon the fracture planes that develop in the rock as it breaks apart.

The authors are greatly indebted to L. Polaski, NASA Ames Research Center, for his assistance during the tests and the preparation of this report. We sincerely appreciate the support and guidance given to us by A. Foster,

C. Dalton, W. Jacobi, and C. Wilson, Sandia Laboratory, while preparing for and conducting the tests at the Tonopah Test Site, Nevada.

In compliance with the NASA's publication policy, the original units of measure have been converted to the equivalent value in the Système International d'Unités (SI). As an aid to the reader, the SI units are written first and the original units are written parenthetically thereafter. Field measurements, which were performed to within $\pm 1/4$ inch, are converted to the nearest centimeter.

PROCEDURE

Thirteen scaled penetrators were fired into prepared targets at the Sandia Tonopah Test Range, Nevada, during April 16 to 28, 1979. The firings were conducted with 0.63-scale, 1 solid penetrators (steel alloy 4340). The penetrators were 62.86 centimeters (24.75 inches) long and 5.71 centimeters (2.25 inches) in diameter and were painted white with 0.63-centimeter (0.25 inch) wide black stripes every 7.6 centimeters (3 inches) along the body (fig. 1). The targets consisted of three different arrangements of rocks buried beneath or lying on the homogeneous compacted dry playa sediments (fig. 2). The first series of tests consisted of penetrator impacts into layers of rocks (15-centimeter (6 inch) thick layers of 2- and 5-centimeter (3/4 and 2 inch) diameter rocks and single layers of 13-, 18-, and 61-centimeter (5, 7, and 24 inch) diameter rocks) buried 30 centimeters (12 inches) below the playa surface. The second series of tests consisted of penetrator impacts into single rocks (5, 13, 18, and 61 centimeters (2, 5, 7, and 24 inches) in diameter) lying on the playa surface. The third series of tests consisted of penetrator impacts into layers of rocks (a 15-centimeter (6 inch) thick layer of 5-centimeter (2 inch) diameter rocks and single layers of 13- and 18-centimeter (5 and 7 inch) diameter rocks) lying on the playa surface. In each test, the penetrator was alined to strike a target rock that had been selected by boresighting the gun at a half-radius point.

The rock selected for this test was a basalt from the Malpais lava flow near Tularosa, New Mexico, that had been removed by jackhammer, then crushed and sized. This basalt, a tholeitte having a porosity of 20 to 30 percent, was selected because of its similarity to Martian volcanic rocks (ref. 2). The type of flow varies from pahoehoe to aa. Before this basalt was selected, field tests were conducted in the Malpais with 0.63-scale penetrators (ref. 3). The depth of penetration was about 61 centimeters (24 inches) during these tests; thus, the volcanic rock had an S number of less than 1 (about 0.7) in accordance with Young's penetration equations (ref. 4), which verified similarity with previous tests in terrestrial analogs of Martian volcanic rocks.

The 7.6-centimeter (3 inch) diameter air gun used to fire these penetrators was operated by Sandia staff from Albuquerque, New Mexico. Because the

¹Scaled to Mars penetrator configuration based on diameter, where the ratio of weight to cross-sectional area W/A is kept constant.

inside diameter (7.818 centimeters (3.078 inches)) of this air gun was too large for the 0.63-scale penetrator (5.71 centimeters (2.25 inches) diameter), an aluminum sabot was used to guide the projectile down the gun barrel (fig. 3). The aft end of the penetrator was mounted in the sabot and held with three setscrews. The sabot and the penetrator were mounted in the breech (fig. 4), where another setscrew was used to hold the sabot-penetrator assembly and prevent it from falling out when the gun was erected to the vertical position. However, on one test, the penetrator fell as the gun was erected and broke the target rock. The target was rebuilt using another rock before firing the shot (test 4). Although the sabot was stripped from the penetrator by a wood block, on six tests, the sabot went through the block and impacted the ground about 150 milliseconds after the penetrator disappeared from the field of view.

The orientation of the air-gun barrel after being erected (fig. 5) was measured in two directions along the same axis as the grid frame staked to the ground as a basis of reference for photography. The orientation of the air gun was within $\pm 0^{\circ}40^{\circ}$ of vertical for all tests (table I). The air-gun tank pressure at firing was 10 997 kN/m² (1595 lb/in²), which produced an impact velocity of 150 m/sec (492 ft/sec) for the penetrator (fig. 6).

An L-shaped metal frame painted orange, having 1.3-centimeter (0.5 inch) bars welded in a grid pattern on 15.2-centimeter (6 inch) intervals (fig. 7), was used as a reference for tracking penetrator movement. This grid was leveled using a Brunton compass for tests 4 to 13; the orientation of the grid is not precisely known for tests 1 to 3.

Photographic coverage of the tests consisted of two types of high-speed motion and 70-millimeter still photography. The high-speed motion pictures were taken of all tests except when the film broke or the camera jammed. 2 Two Milliken cameras, having a film speed of about 400 frames/sec, were used to obtain overall views of the air gun, of the penetrator impact event, and of debris flying from the impact. One Hycam and one Fastax camera, each having a film speed of about 10 000 frames/sec, were used to obtain closeup views of the penetrator. These cameras were positioned perpendicular to the grid frame (fig. 8) to enable reconstructing a three-dimensional orientation for the penetrators during flight and impact. Other uses of these high-speed motion pictures include measuring impact velocity, deceleration, and lateral displacements and documenting rock failure during impact. Timing marks were exposed on the films to assist photointerpretation. Although a timing signal of 10 000 hertz was attempted on all high-speed photography, only 100- and 1000-hertz signals occurred on six films and six films had only an incomplete interrange instrumentation group (IRIG) format A signal or none at all. The lack of reliable shortperiod timing signals seriously limits the photointerpretation activity. photograph (70 millimeter) coverage of the cratered area after impact (fig. 9) was taken in stereo; down-hole photography was obtained of each test to enable making a photomosaic of the entire hole along its longitudinal axis.

 $^{^2\}mathrm{No}$ film was obtained from one of the two Milliken cameras on tests 4 and 6 and from the Hycam camera on tests 8 and 9.

A drill rig with a large bucket auger (fig. 10) was used to drill a 1.2-meter (4 foot) diameter hole adjacent to the point of impact (fig. 11); by this means, a cross section could be made of the entire length of the hole (fig. 12). The final orientation of all penetrators was measured in situ.

RESULTS AND DISCUSSION

The pretest conditions listed in table I include the test number, the rock size, the target arrangement, and the orientation of the air gun, the sabot catcher block, and the grid frame. The post-test conditions listed in table II include the orientation of the penetrator at different depths as it passed through the ground to its final location, the lateral displacement of the penetrator nose from its point of impact to its final resting place, the distance material was thrown away from the point of impact, and the status of the sabot.

The general trend indicates that the larger rocks produced greater angles of deflection for impacting penetrators. For layers of buried rocks (tests 1 to 5), the 2-centimeter (3/4 inch) diameter rocks induced about the same deflection as the 13-centimeter (5 inch) diameter rocks. However, the 18- and 61-centimeter (7 and 24 inch) diameter rocks produced progressively greater angles of deflection, 10° and 11°30', respectively. A noteworthy feature of test 5 is that the penetrator apparently passed through an angle of deflection of 260 about 61 centimeters (24 inches) beneath the surface as it followed the fracture plane produced when the rock broke apart, yet its final orientation about 190 centimeters (75 inches) deep showed a much smaller angle of deflection (11°30'). For layers of surface rocks (tests 9, 10, and 12), only small angles of deflection were observed. Test 10 had the greatest angle, 2°30'. For single rocks at the surface (tests 6 to 8, 11, and 13), the angle of deflection increased gradually as the rock diameter increased. For the 5-, 13-, and 18-centimeter (2, 5, and 7 inch) diameter rocks, the angles of deflection were 2000', 9000', and 8020'. The greatest angles of deflection were observed when the penetrator impacted rocks with a diameter of 61 centimeters (24 inches). The angles of deflection were 19000' and 56010'. In shot 11, the penetrator passed through a large angle of deflection (60°) about 38 centimeters (15 inches) beneath the surface as it followed the fracture plane where the rock broke apart. Again, the penetrator's path straightened as it continued to travel, and its final angle of deflection was only 190. It was not possible to measure the maximum angle of deflection by reconstructing the rock in shot 13 because the target moved as the penetrator was uncovered.

The size of rock necessary to prevent breakage when the penetrator passes through or is captured is a question that should be studied. Previous tests in basalt at Amboy Crater, California (ref. 5), and Tularosa, New Mexico (ref. 3), did not produce angles of inclination larger than a few degrees. In these tests, the penetrator was captured in the basalt and the rock did not break apart.

A cross section of the path of each penetrator through the ground is shown in figure 13. To compare the orientation of the penetrator in the air

gun before firing with its orientation during free flight and in the ground after the test, the data from tables I and II and from the high-speed motion pictures have been plotted on a cyclographic projection (fig. 14). The orientation of the penetrators in the gun and in the ground has been plotted on the figure for all tests. However, free-flight orientation of the penetrators is shown for only 7 (tests 5, 6, 7, 10, 11, 12, and 13) of the 13 tests. Data were not plotted for tests 1, 2, 3, and 4 because of poor image quality and for tests 8 and 9 because only a single film was obtained. Films from both cameras (Fastax and Hycam) are required to plot the true orientation of the penetrator during free flight. A single film provides only an apparent orientation.

If the orientations of the penetrator in the air gun, during free flight, and in the ground were identical, then the various symbols from a single test would plot in the same location (e.g., test 12). An evaluation of the orientations indicates that the gun and free-flight penetrator azimuths are within 1° for 4 (tests 5, 6, 12, and 13) of the 7 tests that can be evaluated. When the free-flight and in-ground penetrator orientations are compared, the azimuths are within 45° for 5 (tests 6, 7, 10, 12, and 13) of the 7 tests, and the dips are within 10° for 11 of the 13 tests.

The high-speed motion pictures show the penetrator usually impacted the surface at some small angle off vertical (probably a consequence of the sabot being stripped from the penetrator). The penetrator path appears to straighten and becomes more vertical as it enters the ground. Typically, an elliptical entry hole is produced that gradually becomes circular at a depth of about 45 centimeters (18 inches).

Although the tests are not conclusive, the data indicate that, for most tests, the final orientation of the penetrator in the ground is related to its free-flight orientation, so long as the impact is within 4° of vertical. This observation holds for impacts into rock sizes as great as 10 times the diameter of the penetrator.

The high-speed motion pictures show the penetrator entering the field of view of the camera at angles inclined to the vertical grid frame as high as 50. The greatest angle the penetrator could have in the gun barrel, as long as the penetrator and sabot are together, is 0.2°. Even if the penetrator and sabot somehow separated inside the barrel, the angle could still not be greater than 1.90. Consequently, the penetrator must be deflected after it leaves the muzzle. Although the evidence is circumstantial, the change in penetrator orientation during flight most probably occurs as the sabot is stripped from the penetrator by the wood block. Since this problem was not known during the tests because of poor quality or undeveloped film, the flight of the sabot-penetrator assembly leaving the muzzle before impacting the wood block was not photographed. The photography was taken only after the penetrator cleared the block. Because the seriousness of the problem was not recognized until after the tests were completed and all the film was developed, only casual information is available to document the problem.

After the first seven shots, in which the sabot passed through a single block six of seven times, two blocks were installed to stop the sabot. The dual-block arrangement was effective; the sabot stopped just short of full penetration of the first block. Typically, the top block had a pronounced asymmetrical bulge of shattered wood on its bottom surface after the shot. On the basis of two observations, the bottom block had black scrape marks oriented 180° apart along the interior walls of the center hole. High-speed photography from all tests except 2 and 9 show at least one scrape mark on one side of the penetrator. The center of the first scrape or scrapes typically occurs about 11 centimeters (4-1/4 inches) from the tip of the nose. A second and third series of scrapes occur on shots 10, 11, and 12 approximately 41 and 57 centimeters (16 and 22-1/2 inches) from the tip of the nose. The motion of the penetrator and/or block whereby paint can be selectively and somewhat consistently abraded remains unclear. Table III summarizes the position of the scrape marks.

It is uncertain whether photointerpretation of the high-speed motion pictures will solve the problems enumerated previously because the quality of the images is very poor for most tests. Most frequently, the black horizontal stripes on the penetrator cannot be seen without special processing, and even in the best films, the stripes are blurred and/or faint. Also, in some cases, the grid frame cannot be adequately referenced because it began vibrating from the airblast before the penetrator passed the grid. Unfortunately, the lack of 10 000-hertz timing marks on 12 of the 24 films causes a serious difficulty for any time-dependent measurements or calculations, and it may not be possible to overcome the loss of a time base. Table IV shows the current status of the high-speed motion pictures for the 13 tests (24 films). There are only four tests for which films from two different views 90° apart have the 10 000-hertz timing marks, and only two of these four tests have usable images.

Results of these tests must be evaluated with current information about the type and size of Martian surface rocks before any predictions can be made about penetrator survival on a Mars mission. Full-scale penetrators having the mission configuration and equipped with umbilicals and afterbodies should be considered for future testing and development studies. Full-scale tests would eliminate the uncertainties associated with scaling and modeling the effects of the impact.

CONCLUSIONS

The following conclusions and recommendations are based on the penetrator field tests.

1. It appears that surface layers and buried layers of rocks which have diameters as large as about 3 times the penetrator diameter cause only small (<10°) angles of deflection of the penetrator during its passage. Typically, single rocks at the surface cause greater deflections, and, as the rock diameter increases, so does the final angle of deflection of the penetrator.

- 2. Only large single rocks (>10 times the penetrator diameter) caused deflections appreciably greater than 10° . Even then, during two tests (tests 5 and 11), the penetrator curiously showed a tendency to become more vertical as it continued its passage through the ground.
- 3. The large deflection angles followed by the penetrator are a consequence of the fracture planes that develop in the rock as it breaks apart. Just how large a rock must be before the penetrator passes through it (or stops in it) without the rock breaking apart is a question which needs to be addressed. Previous tests in basalt at Amboy Crater, California, and Tularosa, New Mexico, did not produce angles of inclination larger than a few degrees, and the penetrator did not pass through the basalt breaking the rock apart.
- 4. Results of these tests must be evaluated with current information about the type and size of Martian surface rocks before any predictions can be made about penetrator survival on a Mars mission.
- 5. Full-scale penetrators having the mission configuration and equipped with umbilicals and afterbodies should be considered for future testing and development studies. Full-scale tests would eliminate the uncertainties associated with scaling and modeling the effects of the impact.

Lyndon B. Johnson Space Center
National Aeronautics and Space Administration
Houston, Texas, September 20, 1979
152-85-00-00-72

REFERENCES

- Manning, Larry A., ed.: Mars Surface Penetrator: System Description. NASA TM-73243, 1977.
- 2. Bunch, T. E.; Quaide, William L.; and Polkowski, George: Initial Basalt Target Site Selection Evaluation for the Mars Penetrator Drop Test. NASA TM X-73111, 1976.
- Nakamura, Yosio; Latham, Gary V.; Frohlich, Cliff; Blanchard, Maxwell B.; and Murphy, James P.: Field Measurements of Penetrator Seismic Coupling in Sediments and Volcanic Rocks. NASA TM-78572, 1979.
- 4. Young, C. W.: Empirical Equations for Predicting Penetration Performance in Layered Earth Materials for Complex Penetrator Configurations. Rep. SC-DR-720523, Sandia Laboratories, 1972.
- 5. Blanchard, M.; Bunch, T.; Davis, A.; Shade, H.; Erlichman, J.; and Polkowski, G.: Results of Analyses Performed on Basalt Adjacent to Penetrators Emplaced Into Volcanic Rock at Amboy, California, April 1976. NASA TP-1026, 1977.
- 6. Bloss, F. Donald: An Introduction to the Methods of Optical Crystallography. Holt, Rinehart and Winston (New York), 1961, pp. 214-223.

9

TABLE I.- PRETEST CONDITIONS

Test no.	Rock diam, ^a cm (in.)	Rock arrangements	Trailer bearing	Orientation of grid frame O		Orientation	of air gun	Orientation of sabot catcher block		
				Bearing	Dip	Bearing	Dip	Bearing	Dip	
1	2 (3/4)	Buried layer	Е	SE	(b)	SE	90°00'	(b)	(b)	
		•		SW	(b)	NE	89°31'	(b)	(b)	
2	5 (2)	Buried layer	E	SE	(b)	SE	90 ⁰ 00'	(b)	(b)	
		•		SW	(b)	SW -	90°00'	(b)	(b)	
3	13 (5)	Buried layer	E	SE	(b)	SE	90°00'	(b)	(b)	
				SW	(b)	SW	89 ⁰ 50'	(b)	(b)	
4	18 (7)	Buried layer	115°	150°	Vertical ^c	150°	900001	(b)	(b)	
		•		240°	Vertical ^c	60°	89040'	(b)	(b)	
5	61 (24)	Buried layer	156°	190°	Vertical ^c	190°	90000'	(b)	(b)	
				280°	Vertical ^c	100°	89°30'	(b)	(b)	
6	5 (2)	Single rock	85°	125°	Vertical ^c	125°	900001	(b)	(b)	
		at surface		215°	Vertical ^c	215°	90 ⁰ 00'	(b)	(b)	
7	13 (5)	Single rock	112°	145°	Vertical ^c	145°	90°00'	(b)	(b)	
		at surface		235°	Vertical ^c	55°	89°30'	(b)	(b)	
8	18 (7)	Single rock	155°	180°	d90°00'	180°	90°00'	(b)	(b)	
		at surface		270°	d90000'	270°	89°30'	(b)	(b)	
9	5 (2)	Layer on	28°	60°	d90000'	60°	90°00'	60°	0°40'	
		surface		150°	d900001	150°	90000'	330°	00501	
10	13 (5)	Layer on	84°	123°	d90000'	123°	900001	123°	0040'	
		surface		2130	d90000'	330	89050'	213°	00401	
11	61 (24)	Single rock	155 ⁰	197 ⁰	d90°00'	197°	90°00'	17 ⁰	00301	
	• •	at surface		287°	d90000'	107°	89050'	107°	00201	
12	18 (7)	Layer on	28°	80°	d90000'	80°	90000'	260°	00101	
	• •	surface		170°	d90000'	350°	89°20'	350°	00401	
13	61 (24)	Single rock	115°	160°	d90000'	160°	900001	160°	00101	
	()	at surface		250°	d900001	250°	900001	70°	0°201	

 $^{^{}a}$ Measured to within $\pm 1/4$ inch. b Not available. c Measured to within $\pm 1^{\circ}$. d Measured to within $\pm 0^{\circ}$ 10'.

TABLE II.- POST-TEST CONDITIONS

Test no.	Orientation d	uring penetra	tion	Max lateral displacement of	Distance debris	Sabot location	
	Depth, a cm (in.)	epth, a cm (in.) Bearing Dip		nose, a cm (in.)	hole, am (ft)		
1	157 (62)	305°	880001	(b)	(ъ)	Hole	
	262 (103)	1300	87°20'				
	335 (132)	143°	86°20'		4. 3		
2	122 (48)	210°	89°30'		(b)	Block	
	236 (93)	285°	88 ⁰ 50'				
	323 (127-1/4)	60°	89 ⁰ 20'	30 (12)	4		
3	76 (30)	272°	87 ⁰ 10'	(b)	(b)	Hole	
	203 (80)	295°	87°00'				
	328 (129-1/4)	320°	86°40'		<i>(-</i>)	_	
4	15 (6)	(b)	88°00'		(b)	Hole	
	140 (55)	270	82°00'				
	264 (104)	20°	80°00'				
	327 (128-3/4)	20°	80°00'	47 (18-1/2)			
5	61 (24)	160°	64°00'		(b)	Hole	
	190 (74-3/4)	125°	78°30'	61 (24)			
6	96 (38)	77°	87°50'		28 (91)	Hole	
	188 (74)	110°	88°20'				
	332 (130-3/4)	112°	88°00'	9 (3-3/4)			
7	341 (134-1/4)	45 ⁰	81°00'	53 (21)	43 (142)	Hole	
8	39 (15-1/2)	152°	87°10'		34 (112)	Block	
	69 (27)	140°	81°40'				
	327 (128-3/4)	140°	81°40'	29 (11-1/2)			
9	340 (133-3/4)	260°	89°20'	11 (4-1/2)	6 (20)	Block	
10	327 (128-3/4)	60°	87°30'	16 (6-1/4)	>30 (>100)	Block	
11	38 (15)	(b)	30°00'		7 (24)	Block	
	213 (84)	310°	71 ⁰ 00'	51 (20)			
12	327 (128-3/4)	260°	89 ⁰ 40'	2 (1)	3 (11)	Block	
13	119 (47)	150°	33 ⁰ 50'	98 (38-3/4)	30 (99)	Block	

^aMeasured to within ±1/4 inch. ^bNot available.

TABLE III.- LOCATION OF SCRAPE MARKS^a ON PENETRATOR AFTER CLEARING CATCHER BLOCK BUT BEFORE IMPACTING TARGET

Test no.	Approx. distan from tip of n of sc	ose to center	Comments					
	Hycam view	Fastax view	,					
1	?	11 (4-1/2)	Hycam image poor; penetrator may be scraped at 11 cm (4-1/2 in.)					
2	No scrapes	No scrapes	Penetrator paint undamaged					
3	15 (6)	15 (6)	Single scrape photographed by both cameras					
4	11 (4-1/2)	11 (4-1/2)	Two separate scrapes, one shown from each camera					
5	11 (4-1/2)	11 (4-1/2)	Single scrape photographed by both cameras					
6	13 (5)	13 (5)	Two separate scrapes, one shown from each camera					
7	10 (4)	10 (4)	Two separate scrapes, one shown from each camera					
8	No photography	11 (4-1/2)	Two separate scrapes shown from one camera					
9	No photography	No scrapes	Penetrator paint undamaged					
10	11 (4-1/2)	11 (4-1/2)	Two separate scrapes, one shown from each camera					
	42 (16-1/2)	No scrapes	Single scrape shown only by one camera					
	57 (22-1/2)	No scrapes	Single scrape shown only by one camera					
11	11 (4-1/2)	11 (4-1/2)	Two separate scrapes, one shown from each camera					
	42 (16-1/2)	42 (16-1/2)	Two separate scrapes, one shown from each camera					
	57 (22-1/2)	57 (22-1/2)	Two separate scrapes, one shown from each camera					
12	10 (4)	11 (4-1/2)	Two separate scrapes, one shown from each camera					
	41 (16)	No scrapes	Single scrape shown only by one camera					
	51 (20)	No scrapes	Single scrape shown only by one camer.					
13	13 (5)	13 (5)	Two separate scrapes, one shown from each camera					

aScrape marks are defined as locations where the white paint on the surface of the penetrator has been abraded away exposing a black undercoat, zinc chromate primer, or bare metal. Scrape areas typically cover several square inches. bMeasured to within $\pm 1/4$ inch.

TABLE IV. - STATUS OF HIGH-SPEED MOTION PICTURE FILM

Shot no.	Camera, station	Description of image	Quality rating (a)	Timing original, Hz
1	Hycam, 1	See 5 stripes, all are blurred and 1 cm (1/2 in.) thick	E	Incomplete IRIG A
	Fastax, 2	See 7 stripes, last one is very faint	F	No IRIG A
2	Hycam, 1	See 7 stripes	F	Incomplete IRIG A
	Fastax, 2	See 7 stripes	F	No IRIG A
3	Fastax, 2	See 7 stripes, faint	F	No IRIG A
	Hycam, 1	See 7 stripes	F	Incomplete IRIG A
4	Hycam, 1	See 7 stripes	A	10 000 100
_	Fastax, 2	See 7 stripes, 3 are very faint	В	10 000 1 000
5	Fastax, 2	See 7 stripes, all are blurred and 1 cm (1/2 in.) thick, last 2 very faint	В	10 000 1 000
_	Hycam, 1	See 7 stripes, last 2 very faint	В	10 000 1 000
6	Hycam, 1	See 7 stripes, all very faint	В	10 000 100
_	Fastax, 2	See 7 stripes for 50 percent of field of view only	В	10 000 1 000
7	Hycam, 1	See 7 stripes, all very faint	В	10 000 100
_	Fastax, 2	See 5 stripes, all blurred and <u>very</u> faint	E	10 000 1 000
8	Fastax, 2	See penetrator nose only	E	10 000 1 000
	Hycam, 1	No film	G	
9	Fastax, 2	See penetrator nose only	Е	10 000 1 000
	Hycam, 1	No film	G	
10	Fastax, 2	See 7 stripes, blurred and very faint	C	1 000
11	Hycam, 1	See 7 stripes, sharp image	D	100
11	Hycam, 1	See 7 stripes, sharp image	D	100
1.0	Fastax, 2	See 7 stripes	C	1 000
12	Hycam, 1	See 7 stripes, sharp image	A	10 000 100
1.2	Fastax, 2	See 5 stripes, only at edge of penetrator	E	1 000
13	Hycam, l	See 7 stripes, sharp image	A	10 000 100
	Fastax, 2	See 7 stripes, very faint only at edge of penetrator	С	1 000

^aQuality rating assigned after four successive film processing improvements. Key to quality rating of films after fourth processing: A, see seven stripes sharp enough to measure, has 10 000-hertz timing marks (three films); B, see seven stripes but some may be too faint to measure, has 10 000-hertz timing marks (six films); C, see seven stripes but some may be too faint to measure, has 1000-hertz timing marks (three films); D, see seven stripes sharp enough to measure, has only 100-hertz timing marks (two films); E, see one or more stripes but some (or all) may be too faint to measure, has 10 000-, 1000-, or 100-hertz timing marks (five films); F, see seven stripes which may be sharp or faint but has no timing marks (five films); and G, cannot see penetrator (two shots).




Figure 1.- Mars penetrator (0.63 scale) configuration fired in tests at Tonopah, Nevada, in April 1979.




Figure 2.- Layout of test site. The penetrator impact points are located at one-half the radius of the rock. Test numbers are shown beneath each target arrangement.




Figure 3.- Sabot used to adapt penetrator to 7.6-centimeter (3 inch) air gun.




Figure 4.- Penetrator and sabot assembled and mounted in breech of air gun.




Figure 5.- Air gun shown in vertical position (orientation from which measurements were made) and grid frame located beneath trailer before test 6. Camera pallets are located on the ground near the front and rear of the trailer.




Figure 6.- Penetrator being fired by air gun (test 6). The blast of air which emplaces the penetrator produces the cloud of dust obscuring the grid and the target.




Figure 7.- Grid network that provided a three-dimensional frame of reference for the high-speed motion pictures. The grid consisted of 1.3-centimeter (0.5 inch) aluminum bars welded together at 15.2-centimeter (6 inch) intervals. The grid was staked to the ground to prevent movement during the tests, but airblast-produced vibration occasionally blurred the image of the grid in the films.




Figure 8.- Layout of motion picture cameras, grid frame, and penetrator impact point.




Figure 9.- Cratered area after penetrator passed through the 13-centimeter (5 inch) diameter rock shown in figure 7. The penetrator stopped approximately 4 meters (12 feet) beneath the surface after impact. Several broken fragments of the original rock are near the grid.




Figure 10.- A 1.2-meter (4 foot) diameter hole was drilled with a bucket auger adjacent to the hole made by the penetrator.



Figure 11.- One side of the hole was removed to expose a complete cross section of the hole made by the penetrator.






Figure 12.- Cross section of the hole made by the penetrator in test 2. The distance from the surface of the ground to the nose of the penetrator is 323 centimeters (127 inches). The penetrator had a final orientation of 89°20' from the horizontal along a bearing of 60°. A change in direction occurred just after the penetrator passed through the 5-centimeter (2 inch) diameter rocks.




(a) Tests 1 to 3.

Figure 13.- Cross sections of the hole after each penetrator test.




(b) Tests 4 to 6.

Figure 13.- Continued.




(c) Tests 7 to 9.

Figure 13.- Continued.



(d) Tests 10 to 12.

Figure 13.- Continued.




NOTES

- 1. These diagrams have been reconstructed from field measurements and are intended to show only major changes in penetrator direction. The diagrams only approximate the actual penetrator movement.
- 2. The diagrams only approximate the location and shape of the rocks the penetrator encountered. Rock boundaries have been omitted for clarity in plan views of tests 1 to 10 and 12.

(e) Test 13.

Figure 13.- Concluded.



- A Free-flight orientation
- O Final orientation

Figure 14.- A cyclographic projection showing penetrator orientations for each test. Three points were plotted for tests 5, 6, 7, 10, 11, 12, and 13: orientation in the air gun (data from table I), orientation during free flight (data from high-speed motion pictures), and final orientation (data from table II). Two points were plotted for all other tests: orientation in the air gun and final orientation. The bearing for each point is read on the outside perimeter as a compass direction. The dip angle is read along a radius from the origin to either E or W using the graduated 10° increments from 0° to 90°. The procedure used to locate these points is described in reference 6.

				· · · · · · · · · · · · · · · · · · ·
1. Report No. NASA TM-58222	2. Government Accession	on No.	3. Recipient's Catalog	No.
4. Title and Subtitle PRELIMINARY RESULTS OF PENETE PROGRAMTONOPAH, NEVADA, APE			5. Report Date October 1979 6. Pérforming Organiza	ation Code
			JSC-16221	
7. Author(s)			8. Performing Organiza	ation Report No.
Maxwell B. Blanchard, Uel Cla				
Mischelle Dalbey, LPI, and Ja	mes P. Murphy, A	RC	10. Work Unit No.	***
9. Performing Organization Name and Address			152-85-00-00-	-72
Lyndon B. Johnson Space Cente Houston, Texas 77058	r		11. Contract or Grant	No.
			13. Type of Report an	d Period Covered
12. Sponsoring Agency Name and Address			Technical Men	norandum
National Aeronautics and Space Washington, D.C. 20546		14. Sponsoring Agency		
15. Supplementary Notes		<u></u>		
Mischelle Dalbey was a summer	intern at the L	unar and Planetary	Institute.	
ritscheffe balbey was a summer	. Intern de ene a	unar ana rianotary	~	
				
16. Abstract Thirteen subscale (0.63 scale)				_
resting on and within compact April 1979. All penetrators ity. Although minor variation of the buried penetrators was the rocks encountered during vealed that surface and buried trator diameter caused only a greater than 10 times the perthan 10°. The large deflection enced by fracture planes that failure of the penetrator occurred penetrator through the surface, and after the tests. penetrator tests, and conclusive performance.	were identical interpretations in impact angle primarily a continuous of rocket and (<10°) angle etrator diameter on angles followed developed in the curred during the ground is shown to Comparisons are	n size, shape, wei le were documented sequence of the si measurements of is having diameters es of deflection. caused deflectioned by the penetrate rock as it broke se tests. A crossogether with detaimade with results	ght, and impact to the final ori tze, shape, and mpacted penetra up to 3 times Only large sin as appreciably a or were strongle apart. No cat a section of the ts on orientati of previous su	e veloc- lentation depth of ators re- the pene- ngle rocks greater ly influ- tastrophic e path of lon before, ubscale
17. Key Words (Suggested by Author(s))		18. Distribution Statement		·
Penetrators Fracture mechanics High-speed cameras Mars exploration Planetary missions			netary Explorat	
19. Security Classif. (of this report)	20. Security Classif. (of		21. No. of Pages	22. Price*
Unclassified	Unclassified		36	\$4.00

•			
,			
·			